
**PHASE I
ENVIRONMENTAL SITE ASSESSMENT**

Dixon Agency Home Site
Lot 6, House #10
Dixon Agency, Montana

Prepared for:

Ms. Marlene McDanal
Confederated Salish and Kootenai Tribes
301 Main Street
Polson, MT 59860

Prepared by:

Geomatrix Consultants, Inc.
1001 South Higgins Avenue, B-1
Missoula, Montana 59801
(406) 542-0129

September 2007
Project No. 12454



**PHASE I
ENVIRONMENTAL SITE ASSESSMENT**

Dixon Agency Home Site
Lot 6, House #10
Dixon Agency, Montana

Prepared for:

**Ms. Marlene McDanal
Confederated Salish and Kootenai Tribes
301 Main Street
Polson, MT 59860**

Prepared by:

**Geomatrix Consultants, Inc.
1001 South Higgins Avenue, B-1
Missoula, MT 59801**

September 2007



TABLE OF CONTENTS

	Page
EXECUTIVE SUMMARY	1
1.0 INTRODUCTION.....	1
1.1 Purpose.....	1
1.2 Reason for Performing the ESA	2
1.3 Scope of Services.....	2
1.4 Exclusions.....	2
1.5 Significant Assumptions	3
1.6 Limitations.....	3
1.7 User Reliance	4
2.0 SITE DESCRIPTION	4
2.1 Location and Legal Description.....	4
2.2 Site and Vicinity General Characteristics.....	4
2.2.1 General Site Setting.....	4
2.2.2 Geology, Hydrogeology, and Soils	4
2.3 Current Use of the Site and Adjoining Parcels.....	5
3.0 INFORMATION PROVIDED BY USER	5
3.1 Title Records and Environmental Liens or Activity and Use Limitations	5
3.2 Specialized Knowledge	5
3.3 Commonly Known or Reasonably Ascertainable Information	5
3.4 Valuation Reduction for Environmental Issues	6
3.5 Owner, Property Manager, and Occupant Information	6
3.6 Other	6
4.0 RECORDS REVIEW	6
4.1 Standard Environmental Record Sources	6
4.1.1 On-site	6
4.1.2 Off-site	6
4.1.3 Orphan Sites	7
4.2 Additional Records Review	7
4.3 Historical Information	7
4.3.1 Historical Aerial Photographs.....	7
4.3.2 Historical Topographic Maps	8
4.3.3 Environmental Lien Records	8
5.0 SITE VISIT	8
5.1 Methodology and Limiting Conditions.....	8
5.2 On-Site Observations.....	8
5.3 Asbestos	8
5.4 Lead-Based Paint.....	9
5.5 Surrounding Properties.....	10

TABLE OF CONTENTS
(Continued)

6.0	INTERVIEWS	10
7.0	PROPERTY OWNER QUESTIONNAIRE	10
8.0	FINDINGS	11
8.1	Data Gaps.....	11
9.0	CONCLUSIONS	11
9.1	Other Considerations	11
10.0	DEVIATIONS	11
11.0	ADDITIONAL SERVICES	11
12.0	REFERENCES	12
13.0	ENVIRONMENTAL PROFESSIONAL SIGNATURE AND STATEMENT	13

TABLES

Table 1	Aerial Photograph Observations	7
---------	--------------------------------------	---

FIGURES

Figure 1	Location Map - Topographic
Figure 2	Site Map

APPENDICES

Appendix A	Topographic Map
Appendix B	ITI Search Report
Appendix C	Aerial Photographs
Appendix D	Site Photographs
Appendix E	Questionnaire